

Vortex8 Release Notes 1.0.33

How to update

1. Copy the file to a USB drive.

*Note: Only one *.sfb update file should be copied onto the drive at a time.*

2. Insert USB drive into USB connector on Vortex.

3. Power up Vortex8 and it will automatically update to the version copied on the USB drive.

Note: Installing will take 1-2 minutes.

4. Safely remove USB drive once the update is complete.

i *Recommended USB drives include EMTEC, Kingston and Toshiba. Drives will need to be formatted as FAT32. If the Vortex8 fails to read the USB drive, please try one from a different manufacturer.*

What's new

Changes from 1.0.30 to 1.0.33

- Added Software Version Number to Splash screen
- Fixed bug where only 1 zone would work after removing DMX with multi-zone mode
- Fixed bug where fans could come on briefly on startup
- Changed LumenRadio signal strength from bar graph to % text display

Known Issues

- When running multi-zone DMX mode, the home screen does not show correct level or colour information for zones and level indicator can flicker between values

What to expect in future updates

- sACN and ArtNET
- WiFi support
- More Effects